



Release Notes Chrysler Group LLC©

wiTECH™ Diagnostic Application Version	14.01.20
wiTECH™ POD Operating System Version	4.0.2
wiTECH™ MicroPOD II Operating System Version	1.2.1
Release Date	July 27th, 2013

Table of Contents

OVERVIEW _____	3
New This Release _____	3
System Requirements _____	3
New or Discontinued Support of Platforms _____	4
Contact Information _____	4
WITECH™ SUPPORTED VEHICLES _____	4
WITECH™ SUPPORT INFORMATION _____	5
New Features _____	5
Fixes _____	5
Known wiTECH Application Issues _____	5

Overview

New This Release

This release addresses reported issues as well as software enhancements; most noteworthy is two new features to assist users in performing future wiTECH software updates from within the application:

- The first software update feature is available when the users receive the software update notification window. If the user is currently too busy to perform the update and selects the “Update Later” option, a button will appear in the application reminding the user that an update is available. This allows an update to be performed by the user when time permits.
- The second software update feature allows a user to check for updates from the “Help” menu at any time by selecting “Check for updates”.

This release has also added new software components that will be installed just before the wiTECH system installs. These components will be utilized in the future for performance improvements and other enhancements.

Finally, vehicle diagnostic and flash support has been added for most 2014 MY vehicles.

For full details of these features and other wiTECH specifics, review the articles and videos at [DCCTools Knowledgebase](#).

System Requirements

Recommended Hardware:

System Type	Processor	HDD Space	Memory	Operating System	Network Adapter	Monitor
Laptop or Tablet	Intel i7 – 620M Dual Core 2.66GHz or Better	80GB	4GB	Windows 7 Professional 32-bit or 64-bit	10/100 wired, and 802.11g wireless	1920x1080 resolution

Minimum Hardware:

System Type	Processor	HDD Space	Memory	Operating System	Network Adapter	Monitor
Laptop or Tablet	Intel i5 – 520M Dual Core 2.4GHz or equivalent	40GB	2GB	Windows 7 Professional 32-bit or 64-bit	10/100 wired, and 802.11b or 802.11g wireless	1024x768 resolution

Software:

Name	Version
Adobe AIR	3.0 or greater
Java	1.6.0_21 or greater
Adobe Reader	9.0 or greater
Internet Explorer	8.0 or greater
SVG Viewer	3.0

Reasons to Upgrade

It is very important for all users to keep their wiTECH Diagnostic Application up-to-date with the latest software version to take full advantage of new enhancements and ensure you're running with optimal functionality.

New or Discontinued Support of Platforms

Microsoft VISTA is no longer supported for wiTECH as of January 1st, 2012.

Contact Information

If you have any questions concerning this release, please contact the wiTECH Help Desk or reference the knowledge base.

- 1.888.witech-1
- [DCCTools Knowledgebase](#)

wiTECH™ Supported Vehicles

Model Year	Vehicles
2004	HB
2005	HB, LX, ND, WK
2006	DR, HB, KJ, LX, ND, PT, WK, XK
2007	CS, DR, HB, HG, JK, JS, KA, KJ, LX, MK, ND, PM, PT, VB, WK, XK, ZH
2008	CS, DR, HB, HG, J8, JC, JK, JS, KA, KK, LC, LX, MK, ND, PM, PT, RT, VB, WK, XK, ZB, ZH
2009	DR, DS, HB, HG, HB/HG-HEV, J8, JC, JK, JS, KA, KK, LC, LX, MK, ND, PM, PT, RT, VB, WK, XK, ZB
2010	D2, DJ, DR (DC/DM), DS, DX, J8, JC, JK, JS, KA, KK, LC, LX, MK, ND, PM, PT, RT, WK, XK, ZB
2011	D2, DD, DJ, DP, DS, DX, J8, JC, JK, JS, KA, KK, LC, LD, LX, MK, ND, PM, RT, WD, WK
2012	D2, DD, DJ, DP, DS, DX, FF, J8, JC, JF, JK, JS, KK, LC, LD, LX, MK, PF, PM, RT, WD, WK
2013	BK, D2, DD, DJ, DP, DS, DX, FF, FF BEV, J8, JC, JF, JK, JS, KK, LC, LD, LX, MK, NY, PF, RT, WD, WK, ZD
2014	BF, D2, DD, DJ, DP, DS, DX, FF, FF BEV, J8, JC, JF, JK, JS, KL, LC, LD, LX, MK, PF, RT, VF, WD, WK, ZD

wiTECH™ Support Information

New Features

MY(s) / Vehicle(s)	ECU	Change Description
2014 WK	PCM	Added ECU support for NAFTA diesel engine controller.
All RA3/RA4	RADIO	Added UConnect Wifi HotSpot diagnostics.
All	All	"Check for updates" added to help menu.
All	All	Added a button to wiTECH that indicates if an update is available and the user selects "Update Later" or cancel the pop-up window.
All	All	KDA and DRB III new update process.
All	All	MicroPODII operating system update to support an " " if included in the SSID.
All	All	wiTECH POD operating system updates.

Fixes

MY(s) / Vehicle(s)	ECU	Change Description
2011-2014 ALL	GPEC PCM	Fixed "Reverse Lockout Solenoid" actuator error of displaying for all applications.
2014 BF	TCM	Updated "Quick Learn" Misc. Function, added delay timer.
2014 WK	AFLS	Fixed "AFLS Calibration" Misc. Function to properly calibrate level-only equipped headlamps.
All	CM848	Fixed issue with CM848 Flash in DRB III Emulator.
All	All	Fixed issue with Program Tire Sensor ID w/TPM Tool
2013 BK	PCM	Fixed PCM displaying not built.
All	All	The Knowledge Base link in the help menu has been changed to "wiTECH Knowledge Base".
All	All	When printing lists only visible data will be printed.

Known wiTECH Application Issues

Issues
"Learn Adaptive Numerator" Misc. Function is displaying on all PCM Variant \$02, it should only display on PCM Variant \$02 Version \$12 and higher on 07-10 JS, MK, PM and 09-10 JC.